



A DIVISION OF CLARKE-GRAVELY CORPORATION

To continue its program of quality and design improvement, the manufacturer reserves the right to change specifications, design or prices without notice and without incurring obligation.

Technical Information

TECHNICAL SERVICE BULLETIN – 1461

TO: ALL GRAVELY OUTLETS

DATE: FEBRUARY 5, 1974

SUBJECT: HARD STARTING IN 10, 12 AND 14 HORSEPOWER
KOHLER ENGINES, K241, K301, AND K321

Enclosed is a reprint of Kohler Service Bulletin No. 100.

We have not received any reported problems with the above engines until the recent cold weather.

Should you have a customer with a starting problem, please check the engine per this Kohler Bulletin.

M. H. Lance, Manager
Customer Service Department

MHL/bh

Attachment