

I M P O R T A N T

Attached are two (2) copies of Technical Service Bulletin 1336 dated February 16, 1970. This bulletin should have accompanied Technical Bulletin 1388, dated February 24, 1971. Please attach Technical Service Bulletin 1336 to Technical Service Bulletin 1388. This information is required to process a battery warranty claim between Gravely and Douglas Company. Claims without this information will be returned.

Sincerely,



Cecil Brake  
Advertising Manager

CB/lh

Enclosures (2)

