



To continue its program of quality and design improvement, the manufacturer reserves the right to change specifications, design or prices without notice and without incurring obligation.

## Technical Information

### TECHNICAL SERVICE BULLETIN - 1417

TO: ALL GRAVELY OUTLETS

DATE: JANUARY 18, 1972

SUBJECT: COMMERCIAL TWO-WHEEL TRACTOR'S CHANGE  
IN INSTRUMENT PANEL

Instrument panel, part number 18314P1, is being cancelled and replaced by instrument panel, part number 10653P3.

Should the instrument panel be required to be replaced on one of the above tractors, equipped with the 18272P1 ignition switch, the switch hole in the 10653P3 panel will have to be opened to 5/8" diameter.

A handwritten signature in cursive script that reads "Mel Lance".

Mel Lance  
Service Manager

ML/lh